

Termination Kit

Part Number: 2950001-01

List of Contents

- Alcohol Dispenser
- Buffer Strippers
- Cable Stripper
- Cleaning Wipes
- Drop Cable (2.0 x 1.6 mm)
- Drop Cable (3.0 x 2.0 mm)
- Fiber Cleaver
- Fiber Cleaver Bag
- Filler Pieces & Cable Holders
- Fiber Stripper

Instructions

Fiber Cleaver

- Place the buffer stripping tool and fiber assembly into the slot.
- Close the lid and slide the blade backwards until it locks into place.
- Open the blade and remove the cleaved fiber. Dispose of the scrapped piece of fiber.

Jacket Stripper

- Insert cable through the stripper to the desired measurement and squeeze the handle.
- Remove the cable from the stripper and slide the jacket off the fiber by hand.

Fiber Stripper

- Select correct strip size: 125 μm , 250 μm , or 900 μm .
- Place fiber inside stripper and squeeze tool until it stops.
- For 900 μm , release tool and pull jacket off by hand. For 125 μm and 250 μm keep the tool compressed and pull the fiber through the stripper to remove the coating.

Note: Angle tool to keep fiber straight while stripping.

Note: Longer sections of 250 μm may need to be stripped in sections rather than all at once.



Bel Fuse Inc.
206 Van Vorst St.
Jersey City, NJ 07302, USA

+1 717.235.7512
techhelp@belf.com
belfuse.com